

THE PERFECT ADAPTER™

FOR RIFLES

This adapter comes with two sleeves. The SMALLER sleeve has a SMALLER hole and is used for cases between .218 ~ .243. The LARGER sleeve is for cases from .270 ~ larger calibers and works great with longer spherical / stick powders. Insert a sleeve from the top with the longer funnel end facing up. The sleeve is free floating and will automatically rise to the height of each case.

Carefully screw the Perfect Adapter onto the Lee Perfect Powder Measure. Be careful not to over-tighten. A very light "finger tight" is all you need. Thread the Perfect Adapter into the standard 7/8-14 threads on your reloading press. Depth is not critical. Index the handle to clear other dies (if mounted in a turret press). Adjust and check the Perfect Powder Measure to consistently throw your desired powder charge.



THE PERFECT ADAPTER™


A registered trademark of Gun-Guides, LLC

WWW.GUN-GUIDES.COM



THE PERFECT ADAPTER™

EXTENDER®



Extends the overall height of our Lee Perfect Powder Adapters® for Handguns or Rifles to accommodate the Lee Safety Prime and other accessories mounted on your reloading press.

Directions: (1) Screw (finger tight) the Lee Perfect Powder Measure into the top of the Extender. (2) Confirm that the o-ring is seated above the threads on the bottom of the Extender. Screw (finger tight) into the top of our LEE Perfect Powder Measure Adapter®. or our LEE Perfect Rifle Adapter®. (3) Insert all three components into the Lee Powder Through Expanding Die or the Lee Rifle Charging Die until it is firmly seated into the cap.

CAUTION: The o-rings are compressed to provide a tight fit. Control the Adapters while disassembling and separating from the funnel cap.




A registered trademark of Gun-Guides, LLC

WWW.GUN-GUIDES.COM



THE PERFECT ADAPTER™

FOR HANDGUNS



Directions: Carefully screw the Perfect Adapter onto the Powder Measure. Be careful not to over-tighten. A very light "finger tight" at the end of the threads is all you need.

Confirm that the O-rings are seated properly into their grooves and insert the adapter into the Lee Powder Through Expanding Die or the Lee Rifle Charging Die until it is firmly seated into the cap (as shown above). If using a turret press, index the handle to clear the other dies.

FOR LEE PERFECT POWDER MEASURES



A registered trademark of Gun-Guides, LLC

WWW.GUN-GUIDES.COM

THE PERFECT ADAPTER™

FOR HANDGUNS



Directions: Carefully screw the Perfect Adapter onto the Powder Measure. Be careful not to over-tighten. A very light "finger tight" at the end of the threads is all you need.

Confirm that the O-rings are seated properly into their grooves and insert the adapter into the Lee Powder Through Expanding Die or the Lee Rifle Charging Die until it is firmly seated into the cap (as shown above). If using a turret press, index the handle to clear the other dies.

For RCBS & ALL 7/8" x 14 POWDER MEASURES



A registered trademark of Gun-Guides, LLC

WWW.GUN-GUIDES.COM